



## MBDA Company Marking NOT PROTECTIVELY MARKED

# **Basic Quality Management Requirements** for suppliers

Between MBDA Deutschland GmbH (hereinafter referred to as "PURCHASER")

and her subcontractor or supplier (hereinafter referred to as "SUPPLIER")

SUPPLIER:				
Address:				
Creditor-Nr.:				
	Name	Org.Unit /Function	Date	Signature
Accepted: (SUPPLIER)		 		
Accepted: (MBDA)				
		 	-	

Date:	10.01.2019	Document-Title:	Basic (	Basic QM-Requirements for suppliers					
Name:	QVB		Basic am requirements for suppliers						
Department:	PAG-F5	Document-Nr.:	Part:	Version:	Art:	Тур:		Page:	
Cage-code:	C0415	60263148	000	00	TDO	QSF		1 von 11	



MBDA Company Marking NOT PROTECTIVELY MARKED

### **Table of Contents**

	Page
Table of Contents	2
1 General	3
<ul><li>1.1 Change History</li><li>1.2 Abstract</li><li>1.3 Referenced Documents (actual release only)</li><li>1.4 List of Terms and Abbreviations</li></ul>	3 3 4 4
2 Basic Requirements	5
2.1 Contract Review 2.2 Quality Management System 2.3 Information Security 2.4 Requirements concerning subSUPPLIERS 2.5 Traceability 2.6 Counterfeit Parts 2.7 Verification 2.8 Documentation 2.9 Measuring / testing equipment 2.10 Operational planning 2.11 Non-conformities / error messages / error cause analysis 2.12 Information Obligation 2.13 Monitoring 2.14 First Article Inspection 2.15 Delivery Documentation 2.16 Employee Qualification 2.17 Special Processes	5 5 5 6 6 6 7 7 7 7 8 8 8 9 9
3 Annandiy	10

Date:	10.01.2019	Document-Title:	Basic QM-Requirements for suppliers						
Name:	QVB		Zacio am rioquiromono for cappiloto						
Department:	PAG-F5	Document-Nr.:	Part:	Version:	Art:	Тур:		Page:	
Cage-code:	C0415	60263148	000	00	TDO	QSF		2 von 11	





MBDA Company Marking NOT PROTECTIVELY MARKED

#### 1 General

Our suppliers make an important contribution to meeting the requirements of our customers and to guarantee the regulatory and legal requirements as well as the fulfillment of our quality standards.

This document represents an important step for the common and future business relationship between the PURCHASER and the SUPPLIER.

The highest goals are the safety of the products and their users and the satisfaction of our customers.

#### 1.1 Change History

Version	Date	Reason of Change/-request	Changed Chapter	Processor
00	10.01.2019	new	n/a	

Table 1: Change History

#### 1.2 Abstract

The decision to admit a supplier depends essentially on his quality capability.

The SUPPLIER is solely responsible for the conformity of the delivered products / services.

These quality assurance requirements (hereinafter: QAR) form the basis of a cooperation and are thereby an integral part of the procurement scope of the PURCHASER. They apply additionally to the quality requirements, specifications or other regulations of the PURCHASER which are included in the order and they supplement the appointments of the order / contract and the standards and regulations underlying the subject matter of the order.

The SUPPLIER shall be obliged to pass on the relevant claims from this document to his subSUPPLIERS and service providers which are required for the manufacturing and to monitor their compliance.

Date:	10.01.2019	Document-Title:	Basic QM-Requirements for suppliers						
Name:	QVB		Busio will requirements for suppliers						
Department:	PAG-F5	Document-Nr.:	Part:	Version:	Art:	Тур:		Page:	
Cage-code:	C0415	60263148	000	00	TDO	QSF		3 von 11	



MBDA Company Marking NOT PROTECTIVELY MARKED

#### 1.3 Referenced Documents (actual release only)

Doc. Nr. (if applicable)	Titel
ISO 9000	ISO 9000 Quality Management Systems – Fundamentals and vocabulary
EN 9100	Quality Management Systems - Requirements for Aviation, Space, and Defense Organizations
DIN EN ISO 9001	DIN EN ISO 9001 Quality Management Systems - Requirements
DIN ISO/IEC 27002	DIN ISO/IEC 27002 Information technology – Security techniques – Code of practice for information security management
AQAP 2110	NATO- Quality Assurance Requirements for Design, Development and Production
AQAP 2210	NATO Supplementary software quality assurance requirements to AQAP 2110 or AQAP-2310
AQAP 2310	NATO- Quality Assurance Requirements for Aviation, Space and Defense Suppliers

Table 2: Referenced Documents

#### 1.4 List of Terms and Abbreviations

Abkürzung/Begriff	Erläuterung
GQAR	Government Quality Assurance Representative
QM / QMS	Qualitymanagement System
FAI	first article inspection
COC	Certificate of Conformity
СР	Counterfeit Product
QSF/QMR	Qualitymanagement Requirements
OEM	Original Equipment Manufacturer
SUP	Suspected Unapproved Part
IPC	Association Connecting Electronics Industries

Table 3: Terms and Abbreviations

Unless explicitly stated otherwise, terms are used as stated in ISO 9000 (see also the appendix).

Date:	10.01.2019	Document-Title:	Basic QM-Requirements for suppliers						
Name:	QVB		Busio Qiii reduirements for suppliers						
Department:	PAG-F5	Document-Nr.:	Part:	Version:	Art:	Тур:		Page:	
Cage-code:	C0415	60263148	000	00	TDO	QSF		4 von 11	



MBDA Company Marking NOT PROTECTIVELY MARKED

#### 2 Basic Requirements

The SUPPLIER is responsible for all products and services (including those of his subSUPPLIERS), which he delivers to the PURCHASER.

#### 2.1 Contract Review

The SUPPLIER checks the contract / order prior acceptance regarding:

- the manufacturability under the requirements concerning quality, delivery date, costs (through experience of previous orders)
- formal and substantive aspects
- supplied documents

and confirms this with the order confirmation.

The SUPPLIER informs the PURCHASER about:

- possible obsolescence
- risks (including risks related to subSUPPLIERS) affecting deadlines, costs, quality, function, performance, lifetime, manufacturability.

#### 2.2 Quality Management System

The SUPPLIER and his subSUPPLIERS and service providers should at least meet the requirements of ISO 9001 - preferably EN 9100. The SUPPLIER ensures that his subSUPPLIERS and service providers also fulfill this requirement (see also 2.4).

SUPPLIERS whose business is geared towards the aerospace industry are expected to receive EN9100 certification.

In the event that his QM certificate has been suspended or expired, the SUPPLIER shall inform the PURCHASER within 14 days. After renewal of his QM certificate, the SUPPLIER has to send a copy to the client promptly and unsolicited.

#### 2.3 Information Security

In order to protect information - in particular intellectual property of the PURCHASER and his client including data u. Requirements - and in order to safeguard the related customer interests, the supplier must use procedures and means to ensure the security of information. The guidelines of DIN ISO / IEC 27002 can be used as a guide.

#### 2.4 Requirements concerning subSUPPLIERS

In general, all requirements and requirements also apply to all subSUPPLIERS and service providers involved in the fulfillment of the contract by the supplier.

The supplier shall:

- maintain a directory of his Suppliers, indicating the status and scope of the approval. This also
  includes contract manufacturing, design offices and software companies.
- provide precise requirements when submitting verification activities to his subSUPPLIER. He shall also maintain a list of delegated verification activities.

The SUPPLIER is responsible for the availability, actuality and feasibility of the documents specified in the order. The SUPPLIER must ensure that documents that have become invalid within his organiza-

Date:	10.01.2019	Document-Title:	Basic QM-Requirements for suppliers						
Name:	QVB		Busio Qiii Requiremento for suppliers						
Department:	PAG-F5	Document-Nr.:	Part:	Version:	Art:	Тур:		Page:	
Cage-code:	C0415	60263148	000	00	TDO	QSF		5 von 11	





NOT PROTECTIVELY MARKED MBDA Company Marking

tion and those of his subcontractors and service providers are withdrawn and the unintentional use of these documents is excluded (see also 2.8).

If procurement or subcontracting of processes, products and services is foreseen, the risks must be determined and managed with regard to supplier selection / change of supplier and the specific commissioning process.

Product requirements, as well as product-specific quality assurance requirements, are specified in the documentation (e.g. drawings, specifications, instructions). The relevant requirements must be passed on to the approved subSUPPLIERS and their service providers required for the product.

#### 2.5 Traceability

The SUPPLIER shall establish and apply a process that ensures the traceability within the entire supply chain (from production to final assembly) of manufacturing and testing processes including the material of the delivery item to the original manufacturer (OEM / OCM) (excluding standard parts).

This traceability method and documentation shall clearly identify the name and location of all of the supply chain intermediaries from the manufacturer to the direct source of the materiel and shall include the item identification and the corresponding date codes, lot codes, heat codes, serializations, unique item identifiers, or batch identifications (excluding standard parts).

#### 2.6 Counterfeit Parts

The SUPPLIER shall ensure that only new and authentic materials are used in material delivered to the PURCHASER.

If traceability is not clearly possible, the components intended for delivery must be examined by a certified laboratory. As a result of this examination a written proof of the technical data according to the specification / data sheet has to be submitted to MBDA Deutschland GmbH before delivery and has to be accepted by it.

The supplier must ensure that there are effective mechanisms so that no counterfeit parts enter the supply chain and the risk is manageable. Each occurrence of such components must be notified to the PURCHASER immediately in writing; the affected components are to be quarantined.

If counterfeit deliveries or suspected counterfeit deliveries have been delivered under the contract, these deliveries can be confiscated. The SUPPLIER must immediately replace these deliveries with deliveries that are acceptable to the PURCHASER.

The PURCHASER may refer counterfeit deliveries to the local or international governmental authorities for investigation and reserves the right to withhold payments as long as the results of such investigations are available.

#### 2.7 Verification

In principle, the verification in development and production shall be planned and presented to the cli-

The supplier shall

- provide (internal) evidence that all manufacturing and testing operations were performed as planned (in accordance with the manufacturing and testing instructions)
- and have been conducted by qualified staff (ref. 2.16)

Date:	10.01.2019	Document-Title:	Basic QM-Requirements for suppliers						
Name:	QVB		busic will requirements for suppliers						
Department:	PAG-F5	Document-Nr.:	Part:	Version:	Art:	Тур:		Page:	
Cage-code:	C0415	60263148	000	00	TDO	QSF		6 von 11	



NOT PROTECTIVELY MARKED MBDA Company Marking

#### 2.8 Documentation

The SUPPLIER shall comply with the following requirements for documented information created and / or stored by him in order to ensure control:

- Prevent the unintended use of outdated documented information by removal or appropriate marking or steering
- Suitable protection of documented information that is processed electronically (e.g. protection against loss, unauthorized changes, unintended changes, damage, physical damage)
- Records must be kept for a period of 20 years (unless otherwise agreed in the contract) from the end of the calendar year in which production ceases.

Before the removal of documented information, the approval of the PURCHASER must be obtained.

#### 2.9 Measuring / testing equipment

The SUPPLIER shall ensure that the measuring and test equipment used by him are suitable and calibrated by an accredited laboratory in order to ensure the product quality of the delivery item. Measuring and test equipment shall be controlled.

If a deviation is detected during a calibration, the SUPPLIER shall evaluate the validity of the tests carried out with the measuring equipment concerned. The Purchaser and GQAR have the right to request a repetition of the measurements made.

This requirement has to be passed to all subSUPPLIERS if applicable.

#### 2.10 Operational planning

The supplier shall plan, implement and control the processes for the fulfillment of the product requirements and services in order to meet the requirements with an acceptable risk within resource-related and deadline restrictions.

FMEA (Failure Mode, Influence and Criticality Analysis) may be used as state of the art method.

#### 2.11 Non-conformities / error messages / error cause analysis

The SUPPLIER shall provide an in time reporting of defective products that have already been delivered to the PURCHASER, especially those that may affect their functionality and safety. The report must contain a precise description of the fault with details of the parts concerned, part numbers, number of affected parts and delivery data.

If requested by the PURCHASER, the supplier applies the 8D method. Processing time generally: 30 working days. For safety-critical components: 5 working days for an interim report. Missing a deadline shall be requested in writing before the deadline.

The supplier is responsible for the root cause analysis and the correction of nonconformities.

The supplier shall create and maintain instructions to ensure that

- a product that does not meet the specified requirements is excluded from unintended use or assembly
- a nonconforming product is clearly marked
- nonconformance's of already delivered products are reported immediately to the PURCHAS-ER

Date:	10.01.2019	Document-Title:	Basic QM-Requirements for suppliers						
Name:	QVB		Dadio am Roquilomonto for supplicito						
Department:	PAG-F5	Document-Nr.:	Part:	Version:	Art:	Тур:		Page:	
Cage-code:	C0415	60263148	000	00	TDO	QSF		7 von 11	

MBDA Company Marking NOT PROTECTIVELY MARKED

Deliveries of non-compliant products shall be approved by the PURCHASER. For this purpose, the nonconformity shall be documented in a construction deviation (MBDA form QM-0214, download in the supplier portal: www.mbda-procurement.de) and submitted to the PURCHASER for approval before delivery.

Approved construction deviations shall be included in the delivery documentation.

#### 2.12 Information Obligation

The SUPPLIER shall inform the client in advance in the following cases:

- Planned relocation of the production site (also temporary)
- Planned process change
- Planned changes of subSUPPLIERS (also temporary)
- Change of the QM system
- Identification of errors and deviations
- First article inspection according to DIN EN 9102
- Before starting work, if a subcontract or order involves or causes concern
  - a critical item.
  - o significant work content and/or design,
  - immature technical solutions
- If an externally provided product is rejected, reworked, or repaired which has been identified as involving risk or supplied by a subSUPPLIER whose selection or subsequent performance has been identified as involving risk. (see also Risk Assessment, Chapter 2.1).

#### 2.13 Monitoring

The SUPPLIER enables the PURCHASER to convince himself of the implementation of the planned QM measures.

Therefore, he grants the PURCHASER, its representatives, its customers and regulatory authorities to the affected areas of all facilities - after prior appointment - free access to documentation, production and testing stations and provides a qualified employee for support free of charge. However, this does not relieve the supplier of the responsibility for the quality of his delivery nor does it preclude subsequent rejection by the PURCHASER or its customers.

The following monitoring events are included:

- supplier audits
- First Article Inspection
- Production line release
- Auditing quality management system
- Clarification of Nonconformities

Therefore the SUPPLIER and his subSUPPLIERs shall

- grant access to all facilities in which the contracted work is carried out,
- · provide information concerning the fulfillment of the contractually agreed requirements,
- grant unlimited possibility to control of the fulfillment of the requirements by the SUPPLIER and his subSUPPLIER

to the PURCHASER.

In the case of a commission according to AQAP-2110 or AQAP-2310, the right of access is extended to the GQAR.

The SUPPLIER will be notified in advance of any official quality assurance measures to be carried out.

Date:	10.01.2019	Document-Title:	Basic QM-Requirements for suppliers						
Name:	QVB		- Daois am Rodanomonio for suppliers						
Department:	PAG-F5	Document-Nr.:	Part:	Version:	Art:	Тур:		Page:	
Cage-code:	C0415	60263148	000	00	TDO	QSF		8 von 11	



MBDA Company Marking NOT PROTECTIVELY MARKED

#### 2.14 First Article Inspection

For drawing parts and assemblies, a first article inspection shall be carried out in accordance with DIN EN 9102. The PURCHASER reserves the right to accompany a FAI at the SUPPLIERs site by authorized representatives and must therefore be informed 14 days before the scheduled date.

The results of the first article inspection must be recorded for all specified properties with target and actual values; any deviations shall be clearly identified.

The first article test report must be made available to the PURCHASER at the latest when the goods are first delivered.

Serial deliveries may only be made after approval of the first article test report by the PURCHASER.

Changes that affect processes, production facilities, tools and CNC programs must be evaluated and documented within a FAI or Delta FAI according to DIN EN 9102.

#### 2.15 Delivery Documentation

The delivery documentation is included in the scope of delivery and, if incomplete, leads to the rejection or blocking of the delivery.

The following proofs shall be provided as part of the delivery documentation:

- Copies of approved deviations (if any)
- Certificates (eg CoC, test certificates in accordance with DIN EN 10204)

#### 2.16 Employee Qualification

The SUPPLIER ensures that only sufficiently qualified personnel are involved in the execution of activities. Therefore he

- determines the required competence for persons who perform activities under his supervision.
- makes sure that these people are competent based on appropriate training, education or experience.
- where appropriate: he initiates actions to acquire the required competence and assess the effectiveness of the measures taken
- maintains adequate documented information as proof of competence

This includes, for example:

- Employees with soldering activities and with optical inspections of solder joints shall be qualified by regular soldering training in accordance with the IPC standard.
- Employees with welding activities shall have a valid certificate for the respective welding process.

#### 2.17 Special Processes

Special processes shall be qualified and approved by the PURCHASER. Significant processes and parameters of specific processes shall be guided by documented procedures.

These include e.g.:

- glueing
- riveting
- · soldering and machine soldering
- painting
- welding and laser welding
- additive manufacturing processes (such as 3D printing)

Date:	10.01.2019	Document-Title:	Basic (	Basic QM-Requirements for suppliers						
Name:	QVB		- Sacro am regamente les suppliers							
Department:	PAG-F5	Document-Nr.:	Part:	Version:	Art:	Тур:		Page:		
Cage-code:	C0415	60263148	000	00	TDO	QSF		9 von 11		





NOT PROTECTIVELY MARKED MBDA Company Marking

#### 3 Appendix

**Definitions** 

#### Counterfeit Product (CP):

Collective term for fake, recycled components which have been fraudulently put into circulation. For easier handling, no distinction is made between CP and SUP. i.e. "Parts of dubious origin / Suspected Unapproved Products (SUP)" are included in CP.

An unauthorized copy, imitation, substitute, or modified part (e. g., material, part, component), which is knowingly misrepresented as a specified genuine part of an original or authorized manufacturer.

#### Fraudulent component:

Electronic component manufactured or distributed under infringement of law.

These include stolen components, components selected by the original equipment manufacturer (OEM) or a user, disassembled components that are recycled and resold as new components. counterfeit components, imitations, replicas, full or partial substitution of trademarks, designs, utility models, patents, Software or copyrights, e.g. for example: components whose manufacture and distribution are not controlled by the original manufacturer, unlicensed imitations of a design, disguised components (original name, reference date / abbreviation or other identifying information, etc. of the original manufacturer), components without silicon chip inside or with a replaced silicon chip that does not match the silicon chip of the original manufacturer.

#### Parts of doubtful origin / Suspected Unapproved Products (SUP)

Designate aviation and aerospace components and equipment that may not be usable (if applicable) as there is a need for clarification with regard to the requirements of aviation law or their implementation for development, production, maintenance or documentation.

In the vast majority of cases, existing doubts can be eliminated by means of a separate clarification. So SUP does not mean a part that is not allowed from the outset, since it is forged or not manufactured according to legal requirements, etc., but at the moment there is a need for clarification.

#### Identity:

Describes all information relating to the characteristics or characteristics of supplies, such as on:

- the original manufacturer or supplier,
- trademarks or other intellectual property rights.
- part numbers, date codes, lot numbers,
- applied test methods and results,
- documentation, warranties, origin, changes, manipulation, recycling, packaging,
- physical condition, prior use and rejection

#### Traceability:

Ability to have an electronic component with full traceability to the original manufacturer.

This traceability implies that each supplier in the supply chain is prepared to declare in writing and in a legally binding manner that he knows and can state his source of supply to the original manufacturer and confirm that the electronic components are brand new and with the appropriate precautionary measures regarding electrostatic discharge ( ESD) and Moisture Sensitivity (MSL). This confirms that the electronic components to be supplied are unused and brand new and free of ESD, moisture or other damage. This ensures that the electronic components are protected by manufacturers' warranties, have their entire service life and function according to the manufacturer's published data sheet,

Date:	10.01.2019	Document-Title:	Basic QM-Requirements for suppliers						
Name:	QVB		- Sucio am requiremente les cupphore						
Department:	PAG-F5	Document-Nr.:	Part:	Version:	Art:	Тур:		Page:	
Cage-code:	C0415	60263148	000	00	TDO	QSF		10 von 11	



MBDA Company Marking NOT PROTECTIVELY MARKED

with the expected component life in the application for which the reliability predictions and product warranties are provided of the OEM.

#### Critical items

Those items (e. g., functions, parts, software, characteristics, processes) having significant effect on the provision and use of the products and services; including safety, performance, form, fit, function, producibility, service life, etc.; that require specific actions to ensure they are adequately managed. Examples of critical items include safety critical items, fracture critical items, mission critical items, key characteristics, etc.

#### Key characteristic:

Critical items Those items (e. g., functions, parts, software, characteristics, processes) having significant effect on the provision and use of the products and services; including safety, performance, form, fit, function, producibility, service life, etc.; that require specific actions to ensure they are adequately managed. Examples of critical items include safety critical items, fracture critical items, mission critical items, key characteristics, etc.

#### **Special processes:**

Processes whose result cannot be verified by subsequent monitoring or measurement without destroying the component.

Date:	10.01.2019	Document-Title:	Basic QM-Requirements for suppliers						
Name:	QVB		- Sacio am Roquitomonio foi cappiloro						
Department:	PAG-F5	Document-Nr.:	Part:	Version:	Art:	Тур:		Page:	
Cage-code:	C0415	60263148	000	00	TDO	QSF		11 von 11	